Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					6.75	
House No 44-375						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	15.80	0.60	0.125	1.19	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					6.75	
House No 45-387 pujari						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	22.60	0.60	0.125	1.70	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.26	
House No 46-99 Naveen						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	21.90	0.60	0.125	1.64	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	

Scanned with CamScanner

Bath						
W/C	1.00	2.50	1.20	0.125	0.38	
Passage Near W.C/Bath	1.00	0.90	1.00	0.125	0.11	
	1.00	1.60	0.90	0.125	0.18	
House No 47-221 Malar					7.21	
F1C1						
EF1	2.00	1.75	1.55	0.125	0.68	
Main Wall	4.00	1.75	1.25	0.125	1.09	
Partition Wall	1.00	19.00	0.60	0.125	1.43	
	1.00	2.90	0.45	0.125	0.16	
Dedt Excavated Column Area	2.00	2.50	0.45	0.125	0.28	
For Flooring	-4.00	0.20	0.38	0.125	-0.04	
Living						
Bed Room	1.00	2.90	3.40	0.125	1.23	
kitchen	1.00	2.50	2.85	0.125	0.89	
Bath	1.00	2.90	1.65	0.125	0.60	
W/C	1.00	2.50	1.20	0.125	0.38	
Passage Near W.C/Bath	1.00	0.90	1.00	0.125	0.11	
	1.00	1.60	0.90	0.125	0.18	
House No 48-220 ammu					6.99	
F1C1						
EF1	2.00	1.75	1.55	0.125	0.68	
Main Wall	4.00	1.75	1.25	0.125	1.09	
Partition Wall	1.00	20.00	0.60	0.125	1.50	
	1.00	2.90	0.45	0.125	0.16	
Dedt Excavated Column Area	2.00	2.50	0.45	0.125	0.28	
For Flooring	-4.00	0.20	0.38	0.125	-0.04	
Living						
Bed Room	1.00	2.90	3.40	0.125	1.23	
kitchen	1.00	2.50	2.85	0.125	0.89	
Bath	1.00	2.90	1.65	0.125	0.60	
W/C	1.00	2.50	1.20	0.125	0.38	
Passage Near W.C/Bath	1.00	0.90	1.00	0.125	0.11	
	1.00	1.60	0.90	0.125	0.18	
House No 49-220/2 Roopa					7.07	
F1C1						
EF1	2.00	1.75	1.55	0.125	0.68	
Main Wall	4.00	1.75	1.25	0.125	1.09	
Partition Wall	1.00	18.20	0.60	0.125	1.37	
	1.00	2.90	0.45	0.125	0.16	
Dedt Excavated Column Area	2.00	2.50	0.45	0.125	0.28	
For Flooring	-4.00	0.20	0.38	0.125	-0.04	
Living						
Bed Room	1.00	2.90	3.40	0.125	1.23	
kitchen	1.00	2.50	2.85	0.125	0.89	
Bath	1.00	2.90	1.65	0.125	0.60	
W/C	1.00	2.50	1.20	0.125	0.38	
Passage Near W.C/Bath	1.00	0.90	1.00	0.125	0.11	
	1.00	1.60	0.90	0.125	0.18	
					6.93	
House No 50-Srinivas						

Scanned with CamScanner

	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	25.40	0.60	0.125	1.91
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28
	Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04
	For Flooring					
	Living	1.00	2.90	3.40	0.125	1.23
	Bed Room	1.00	2.50	2.85	0.125	0.89
	kitchen	1.00	2.90	1.65	0.125	0.60
	Bath	1.00	2.50	1.20	0.125	0.38
	W/C	1.00	0.90	1.00	0.125	0.11
	Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18
						7.47
	House No 51-Rajeswhari					
	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	22.40	0.60	0.125	1.68
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28
	Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04
	For Flooring					
	Living	1.00	2.90	3.40	0.125	1.23
	Bed Room	1.00	2.50	2.85	0.125	0.89
	kitchen	1.00	2.90	1.65	0.125	0.60
	Bath	1.00	2.50	1.20	0.125	0.38
	W/C	1.00	0.90	1.00	0.125	0.11
	Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18
						7.25
	House No 52-324- pungodi					
	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	27.40	0.60	0.125	2.06
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28
	Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04
	For Flooring					
	Living	1.00	2.90	3.40	0.125	1.23
	Bed Room	1.00	2.50	2.85	0.125	0.89
	kitchen	1.00	2.90	1.65	0.125	0.60
	Bath	1.00	2.50	1.20	0.125	0.38
	W/C	1.00	0.90	1.00	0.125	0.11
	Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18
						7.62
	House No 53-268 Rasathi					
	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	21.60	0.60	0.125	1.62
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28

Scanned with CamScanner

Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.19	
House No 54-263 Shabhana						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	16.80	0.60	0.125	1.26	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					6.83	
House No 55-262						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	17.80	0.60	0.125	1.34	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.100	0.99	
Bed Room	1.00	2.50	2.85	0.100	0.71	
kitchen	1.00	2.90	1.65	0.100	0.48	
Bath	1.00	2.50	1.20	0.100	0.30	
W/C	1.00	0.90	1.00	0.100	0.09	
Passage Near W.C/Bath	1.00	1.60	0.90	0.100	0.14	
					6.22	
House No 56-261						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	17.40	0.60	0.125	1.31	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.100	0.99	
Bed Room	1.00	2.50	2.85	0.100	0.71	
kitchen	1.00	2.90	1.65	0.100	0.48	

Checked

Exec. Engineer
Rajarajeshwari Nagara Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 054.

Scanned with CamScanner

Bath	1.00	2.50	1.20	0.100	0.30	
W/C	1.00	0.90	1.00	0.100	0.09	
Passage Near W.C/Bath	1.00	1.60	0.90	0.100	0.14	
					6.19	
House No 57-276 Vedivelu						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	25.40	0.60	0.125	1.91	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.47	
House No 58-284- Periyamma						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	22.80	0.60	0.125	1.71	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.28	
House No 59-281- Lakshman Vasanth						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	20.80	0.60	0.125	1.56	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.13	
House No 60-181 Shaheb/Swami						

Scanned with CamScanner

	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	19.00	0.60	0.125	1.43
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28
	Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04
	For Flooring					
	Living	1.00	2.90	3.40	0.125	1.23
	Bed Room	1.00	2.50	2.85	0.125	0.89
	kitchen	1.00	2.90	1.65	0.125	0.60
	Bath	1.00	2.50	1.20	0.125	0.38
	W/C	1.00	0.90	1.00	0.125	0.11
	Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18
						6.99
	House No 61-157 Yallamma					
	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	20.00	0.60	0.125	1.50
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28
	Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04
	For Flooring					
	Living	1.00	2.90	3.40	0.125	1.23
	Bed Room	1.00	2.50	2.85	0.125	0.89
	kitchen	1.00	2.90	1.65	0.125	0.60
	Bath	1.00	2.50	1.20	0.125	0.38
	W/C	1.00	0.90	1.00	0.125	0.11
	Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18
						7.07
	House No 62-63 159 Harshaf Pinisha					
	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	23.00	0.60	0.125	1.73
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28
	Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04
	For Flooring					
	Living	1.00	2.90	3.40	0.125	1.23
	Bed Room	1.00	2.50	2.85	0.125	0.89
	kitchen	1.00	2.90	1.65	0.125	0.60
	Bath	1.00	2.50	1.20	0.125	0.38
	W/C	1.00	0.90	1.00	0.125	0.11
	Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18
						7.29
	House No 63-161 Jayamma					
	F1C1	2.00	1.75	1.55	0.125	0.68
	EF1	4.00	1.75	1.25	0.125	1.09
	Main Wall	1.00	23.00	0.60	0.125	1.73
	Partition Wall	1.00	2.90	0.45	0.125	0.16
		2.00	2.50	0.45	0.125	0.28

Scanned with CamScanner

Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.29	
House No 64- 177 Chandramma						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	21.20	0.60	0.125	1.59	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.16	
House No 65-73-Bhemabhai Bhimappa						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	20.60	0.60	0.125	1.55	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.11	
House No 66-Lashmibai Manappa						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	20.00	0.60	0.125	1.50	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	

Scanned with CamScanner

Bath						
W/C	1.00	2.50	1.20	0.125	0.38	
Passage Near W.C/Bath	1.00	0.90	1.00	0.125	0.11	
House No 67-kashiram Sangeetha	1.00	1.60	0.90	0.125	0.18	
					7.07	
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	20.40	0.60	0.125	1.53	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					7.10	
House No 68- Santha Ramchandra						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	14.00	0.60	0.125	1.05	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	
Passage Near W.C/Bath	1.00	1.60	0.90	0.125	0.18	
					6.62	
House No 69- 82- Ramachandra Radha Bahi						
F1C1	2.00	1.75	1.55	0.125	0.68	
EF1	4.00	1.75	1.25	0.125	1.09	
Main Wall	1.00	18.40	0.60	0.125	1.38	
Partition Wall	1.00	2.90	0.45	0.125	0.16	
	2.00	2.50	0.45	0.125	0.28	
Dedt Excavated Column Area	-4.00	0.20	0.38	0.125	-0.04	
For Flooring						
Living	1.00	2.90	3.40	0.125	1.23	
Bed Room	1.00	2.50	2.85	0.125	0.89	
kitchen	1.00	2.90	1.65	0.125	0.60	
Bath	1.00	2.50	1.20	0.125	0.38	
W/C	1.00	0.90	1.00	0.125	0.11	

Scanned with CamScanner



Scanned with CamScanner

BRUHAT BANGALORE MAHANAGARA PALIKE

Name Of Work : Construction of Individual Houses in ward no 17 RR Nagar Constituency

Measurement Sheet

First And Part Bill

Item No: 7 — 21.06.21 / 03/06/21

Item Name: KSRB 4.2.2 : Providing and laying in position reinforced cement concrete of Design mix M20 with OPC cement @ 320kgs, with 20mm and down size graded granite metal coarse aggregates @0.69cum and fine aggregtes @ 0.460 cum, with super plasticisers @ 3 liters confirming to is 9103-1999 reafirmed-2008, machine mixed, concrete laid in layers not exceeding 15 cms thick, vibrated for all works in foundation for footings, pedastals, retaining walls, return walls, walls (any thickness) including attached pilasters, columnspillars, posts, struts, buttresses, bed blocks, anchor blocks & plinths etc., including cost of all materials, labour, HOM of machinery, curing, complete but excluding cost of reinforcement as per specifications.

SLNO	CHAINAGE / Land Mark	NO	L (m)	B (m)	D (m)	QTY	REMARKS
	House No 1 -Armugum						
	F1	2.00	1.60	1.40	0.35	1.57	
	EF1	4.00	1.60	1.10	0.35	2.46	
	For Column						
	C1	2.00	0.20	0.38	4.05	0.61	
	C2	4.00	0.20	0.38	3.45	1.04	
	For Plinth Beam Concrete						
	Main Wall	1.00	21.60	0.20	0.40	1.73	
	Partition Wall	1.00	2.90	0.20	0.15	0.09	
		2.00	2.50	0.20	0.15	0.15	
						7.64	
	House No 2-12- Krishnappa						
	F1	2.00	1.60	1.40	0.40	1.79	
	EF1	4.00	1.60	1.10	0.35	2.46	
	For Column						
	C1	2.00	0.20	0.38	4.05	0.61	
	C2	4.00	0.20	0.38	3.45	1.04	
	For Plinth Beam Concrete						
	Main Wall	1.00	25.60	0.20	0.40	2.05	
	Partition Wall	1.00	2.90	0.20	0.15	0.09	
		2.00	2.50	0.20	0.15	0.15	
						8.18	
	House No 3-13- Nagamani						
	F1	2.00	1.60	1.40	0.35	1.57	
	EF1	4.00	1.60	1.10	0.35	2.46	
	For Column						
	C1	2.00	0.20	0.38	4.05	0.61	
	C2	4.00	0.20	0.38	3.45	1.04	
	For Plinth Beam Concrete						
	Main Wall	1.00	19.60	0.20	0.40	1.57	
	Partition Wall	1.00	2.90	0.20	0.15	0.09	
		2.00	2.50	0.20	0.15	0.15	

Checked NBL

Executive Engineer, Rajarajeshwari Nagara Zone, Bruhat Bangalore Mahanagara Palike

Scanned with CamScanner

house No 4-14 Ammayamma)					7.48
F1					
EF1	2.00	1.60	1.40	0.35	1.57
	4.00	1.60	1.10	0.35	2.46
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	19.60	0.20	0.40	1.57
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.48
House No 5-15 Renu Anjali					
F1	2.00	1.60	1.40	0.35	1.57
EF1	4.00	1.60	1.10	0.35	2.46
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	20.20	0.20	0.40	1.62
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.53
House No 6-Shantamma					
F1	2.00	1.60	1.40	0.35	1.57
EF1	4.00	1.60	1.10	0.35	2.46
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	17.00	0.20	0.40	1.36
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.27
House No 7-410- Manjunath					
F1	2.00	1.60	1.40	0.35	1.57
EF1	4.00	1.60	1.10	0.35	2.46
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	20.80	0.20	0.40	1.66
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.58
House No 8-25-Ranganath					
F1	2.00	1.60	1.40	0.35	1.57
EF1	4.00	1.60	1.10	0.35	2.46

Checked

Scanned with CamScanner

For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	23.60	0.20	0.40	1.89	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
House No 9-36-kannan					7.80	
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	24.00	0.20	0.40	1.92	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
House No 10-33-Krishnappa					8.41	
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	22.40	0.20	0.40	1.79	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.28	
House No 11-34-Suresh						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	20.80	0.20	0.40	1.66	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.15	
House No 12-30-kalyani gudamani						
F1	2.00	1.60	1.40	0.35	1.57	
EF1	4.00	1.60	1.10	0.35	2.46	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	24.20	0.20	0.40	1.94	

Scanned with CamScanner

Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.85	
House No 13-110-Kamalamma						
F1						
EF1	2.00	1.60	1.40	0.35	1.57	
	4.00	1.60	1.10	0.35	2.46	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	24.20	0.20	0.40	1.94	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.85	
House No 14-34Munikrishnappa						
F1						
EF1	2.00	1.60	1.40	0.35	1.57	
	4.00	1.60	1.10	0.35	2.46	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	20.40	0.20	0.40	1.63	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.54	
House No 15-44-Soliyappan						
F1	2.00	1.60	1.40	0.35	1.57	
EF1	4.00	1.60	1.10	0.35	2.46	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	23.00	0.20	0.40	1.84	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.75	
House No 16-Kuppanna						
F1	2.00	1.60	1.40	0.35	1.57	
EF1	4.00	1.60	1.10	0.35	2.46	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	18.20	0.20	0.40	1.46	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.37	
House No 17-67/114 Jayalaksmi						
F1	2.00	1.60	1.40	0.35	1.57	

Executive Engineer
Rajarajeshwari Nagara Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 098

Scanned with CamScanner

	EF1	4.00	1.60	1.10	0.35	2.46
	For Column					
	C1	2.00	0.20	0.38	4.05	0.61
	C2	4.00	0.20	0.38	3.45	1.04
	For Plinth Beam Concrete					
	Main Wall	1.00	19.60	0.20	0.40	1.57
	Partition Wall	1.00	2.90	0.20	0.15	0.09
		2.00	2.50	0.20	0.15	0.15
	House No 18- Parvathi					7.48
	F1					
	EF1	2.00	1.60	1.40	0.35	1.57
		4.00	1.60	1.10	0.35	2.46
	For Column					
	C1	2.00	0.20	0.38	4.05	0.61
	C2	4.00	0.20	0.38	3.45	1.04
	For Plinth Beam Concrete					
	Main Wall	1.00	17.80	0.20	0.40	1.42
	Partition Wall	1.00	2.90	0.20	0.15	0.09
		2.00	2.50	0.20	0.15	0.15
	House No.19-98/166-					7.34
	F1					
	EF1	2.00	1.60	1.40	0.35	1.57
		4.00	1.60	1.10	0.35	2.46
	For Column					
	C1	2.00	0.20	0.38	4.05	0.61
	C2	4.00	0.20	0.38	3.45	1.04
	For Plinth Beam Concrete					
	Main Wall	1.00	18.70	0.20	0.40	1.50
	Partition Wall	1.00	2.90	0.20	0.15	0.09
		2.00	2.50	0.20	0.15	0.15
	House No 20-99					7.41
	F1					
	EF1	2.00	1.60	1.40	0.35	1.57
		4.00	1.60	1.10	0.35	2.46
	For Column					
	C1	2.00	0.20	0.38	4.05	0.61
	C2	4.00	0.20	0.38	3.45	1.04
	For Plinth Beam Concrete					
	Main Wall	1.00	16.00	0.20	0.40	1.28
	Partition Wall	1.00	2.90	0.20	0.15	0.09
		2.00	2.50	0.20	0.15	0.15
	House No 21-100/424					7.19
	F1	2.00	1.60	1.40	0.35	1.57
	EF1	4.00	1.60	1.10	0.35	2.46
	For Column					
	C1	2.00	0.20	0.38	4.05	0.61
	C2	4.00	0.20	0.38	3.45	1.04

Scanned with CamScanner

For Plinth Beam Concrete						
Main Wall	1.00	16.60	0.20	0.40	1.33	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.24	
House No 22-73/08 Raja/Doddayya						
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	22.90	0.20	0.40	1.83	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.32	
House No 23- 14/10- Varshamma						
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	22.00	0.20	0.40	1.76	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.25	
House No 24-13/06-Leelamma						
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	27.60	0.20	0.38	2.07	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.56	
House No 25-613-Sarojamma						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	19.80	0.20	0.40	1.58	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.07	

Scanned with CamScanner

House No 26-337-Nanaka Singh						
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	22.20	0.20	0.40	1.78	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.26	
House No 27-343-Govinda Singh						
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	16.40	0.20	0.38	1.23	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.72	
House No 28-351-hera Singh						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	19.60	0.20	0.40	1.57	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.06	
House No 29-350- Harja Singh						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	19.60	0.20	0.40	1.57	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.06	
House No 30-353- Ladko						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						

Checked

Executive Engineer
Rajarajeshwari Division
Bruhat Bangalore Mahanagara Palike
Bangalore - 560 064.

Scanned with CamScanner

C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	19.00	0.20	0.40	1.52	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.01	
House No 31- 354 Raju Singh						
F1						
EF1	2.00	1.60	1.40	0.40	1.79	
	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	18.60	0.20	0.40	1.49	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.98	
House No 32-Manoj Singh						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	22.80	0.20	0.40	1.82	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					8.31	
House No 33-359- Bharath Singh						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	17.20	0.20	0.40	1.38	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.86	
House No 34-363 -Duragamma Parasuram						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	17.20	0.20	0.40	1.38	
Partition Wall	1.00	2.90	0.20	0.15	0.09	

Scanned with CamScanner

	2.00	2.50	0.20	0.15	0.15
					7.86
House No 35-364- Durgamma Venkatesh					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	17.40	0.20	0.40	1.39
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.88
House No 36-368-Gayatri					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	22.80	0.20	0.40	1.82
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					8.31
House No 37-rama					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	15.60	0.20	0.38	1.17
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.66
House No 38-383					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	15.40	0.20	0.40	1.23
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.72
House No 39-384					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82

Scanned with CamScanner

For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	15.40	0.20	0.40	1.23	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.72	
House No 40-385						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	16.00	0.20	0.40	1.28	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.77	
House No 41-378						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	15.80	0.20	0.40	1.26	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.75	
House No 42-377						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						
Main Wall	1.00	15.80	0.20	0.38	1.19	
Partition Wall	1.00	2.90	0.20	0.15	0.09	
	2.00	2.50	0.20	0.15	0.15	
					7.67	
House No 43-376						
F1	2.00	1.60	1.40	0.40	1.79	
EF1	4.00	1.60	1.10	0.40	2.82	
For Column						
C1	2.00	0.20	0.38	4.05	0.61	
C2	4.00	0.20	0.38	3.45	1.04	
For Plinth Beam Concrete						

Checked
A Rep

Executive Engineer
Rural Water Supply Division
Public Health Engineering Deptt.
Zaheerabad- 502 220.

Scanned with CamScanner

Main Wall	1.00	15.80	0.20	0.40	1.26
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.75
House No 44-375					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	15.80	0.20	0.40	1.26
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					7.75
House No 45-387 pujari					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	22.60	0.20	0.40	1.81
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					8.30
House No 46-99 Naveen					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	21.90	0.20	0.40	1.75
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					8.24
House No 47-221 Malar					
F1	2.00	1.60	1.40	0.40	1.79
EF1	4.00	1.60	1.10	0.40	2.82
For Column					
C1	2.00	0.20	0.38	4.05	0.61
C2	4.00	0.20	0.38	3.45	1.04
For Plinth Beam Concrete					
Main Wall	1.00	19.00	0.20	0.40	1.52
Partition Wall	1.00	2.90	0.20	0.15	0.09
	2.00	2.50	0.20	0.15	0.15
					8.01
House No 48-220 ammu					

Scanned with CamScanner